

Oil Field Environmental Incident Summary

Incident: 20150130142222 **Date/Time of Notice:** 01/30/2015 14:22

Responsible Party: SM ENERGY COMPANY

Well Operator: SM ENERGY COMPANY

Well Name: LINDVIG 1-4

Field Name: INDIAN HILL

Well File #: 11151

Date Incident: 1/29/2015 **Time Incident:** 16:00

Facility ID Number:

County: MCKENZIE

Twp: 152

Rng: 101

Sec: 4

Qtr:

Location Description:

Submitted By: Luke Studer

Received By:

Contact Person: Luke Studer
PO BOX 7168
BILLINGS, MT 59103-7168

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building: 3 Mile

Distance Nearest Water Well: 3 Mile

Type of Incident: Other

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	5	Barrels	5	Barrels	5	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 7/27/2015

Clean Up Concluded: 7/14/2015

Risk Evaluation:

None

Areal Extent:

NA

Potential Environmental Impacts:

None

Action Taken or Planned:

Vac truck was in the area and all 5 barrels salt water was recovered. Company personnel cleaned up the spill area.

Wastes Disposal Location: Recovered salt water and contaminated soil hauled to an approved disposal.

Agencies Involved:

Updates

Date: 1/30/2015 ***Status:*** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.